



**VALENCIA COUNTY
BOARD OF COUNTY COMMISSIONERS
RESOLUTION NO. 2023-24**

**DISPOSITION OF CAPITAL ASSETS
TWO TOTALED VEHICLES**

WHEREAS, the Valencia County Board of Commissioners met in a regular meeting, at the Valencia County Administration Building, 444 Luna Avenue, Los Lunas, New Mexico 87031 on Wednesday, March 15, 2023 at 5:00 p.m.; and,

WHEREAS, pursuant to NMSA 1978 Section 4-38-1 (1884) the powers of a county as a body politic and corporate shall be exercised by a board of county commissioners; and,

WHEREAS, NMSA 1978, Section 4-38-13 (1953) provides that board of county commissioners shall have power at any session to make such orders concerning the property belonging to the county as they may deem expedient; and,

WHEREAS, The vehicles presented for disposition were involved in (separate) motor crashes and were each deemed a total loss by the insurance company. These vehicles are as follows:

2007 Ford Super Duty F-250

VIN 1FTSF21P87EB22696

2017 Ford Explorer 4D

VIN 1FM5K8ARXHGC07795

WHEREAS, a designated committee of at least three Valencia County Officials has declared that all of the tangible personal property that is the subject of this resolution meets the criteria set forth in NMSA 1978, Section 13-6-1 (A) (2013) and Section 13-6-2 and each member has duly sworn and subscribed under oath of its finding.

NOW THEREFORE, BE IT RESOLVED, by the Board of County Commissioners of Valencia County that:


1. It finds that the property described or represented by attached Exhibit I and Exhibit II hereto and incorporated with this Resolution by reference consists of property owned by the County of Valencia and is maintained in the County's current Capital Asset Inventory list;
2. A copy of this Resolution and Exhibit I and Exhibit II shall be sent to the State


Auditor and the Local Government Division of the Department of Finance and Administration at least 30 days before the disposal of the property pursuant to NMSA 1978, Section 13-6-1 (B) (2) (2013) and Section 13-6-2;


3. A copy of this Resolution, Exhibit I and Exhibit II, and the findings of the committee shall be made a permanent part of the official minutes of the County and maintained as a public record subject to the Inspection of Public Records Act;
4. The property described or represented in Exhibit I and Exhibit II shall be released to New Mexico Counties insurance claims.


APPROVED, ADOPTED, AND PASSED on this 15th day of March, 2023.


BOARD OF COUNTY COMMISSIONERS


Gerard Saiz
Chair, District I


Jhonathan Aragon
Vice-Chair, District V


Troy Richardson
Commissioner, District II


Morris Sparkman
Commissioner, District III


Joseph Bizzell
Commissioner, District IV


ATTEST

Mike Milam, County Clerk



ASSET DISPOSAL / TRANSFER FORM

This form is to be used when an asset has been identified as surplus, obsolete, or worn out and is to be disposed of via sale, trade-in, or scrapped.
(Disposal Committee Consensus required)

Use also when an asset is loaned or donated to another governmental organization or to another department within Valencia County.
(Does not require Disposal Committee consensus)

Section A – Departmental Staff Details: Please Print

| Department | Department Director | Department's Asset Coordinator: Last Name First Name |
|--------------|---------------------|---------------------------------------------------------|
| Public Works | Lina Benavidez | Bazen, Roland |

Section B – Asset Details (may attach alternative documents, as long as all information is included)

Short Description of Disposal or Transfer: Vehicle Salvaged.

Transferring Asset from(Dept) Public Works

to (Dept) NM Counties Multi-Line Claims

| Asset Number, if known | Serial Number / Tag # | Asset Description | Asset Location | Asset had been assigned to: (may need to update HR file) | HR / IT approval | If Vehicle: Fleet Manager must sign off | Hard Drive Wiped (not just reformatted)* (Yes/No/NA) |
|---------------------------|--------------------------|-----------------------|----------------|-------------------------------------------------------------|---------------------|-----------------------------------------------|---------------------------------------------------------------|
| see attached or fill in: | | | | | | | |
| 58177 | 1FTSF21P87EB22696 | 2007 Ford Truck F-250 | | | | | N/A |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

Section C – Disposal Committee members:

To be signed & dated at Disposal Committee Meeting:

| Name of Member #1 | Position | Signature | Date |
|-------------------|-----------------------|-------------------------|-----------|
| Lina Benavidez | Public Works Director | <i>Lina Benavidez</i> | 2/24/23 |
| Name of Member #2 | Position | Signature | Date |
| Maria Garcia | Indigent Coordinator | <i>Maria Garcia</i> | 2/16/2023 |
| Name of Member #3 | Position | Signature | Date |
| Kendra Kaneshiro | Accountant | <i>Kendra Kaneshiro</i> | 2/16/2023 |

Section D: To be filled out by Finance Department :

| Name of Person Approving | Position | Signature | Date |
|--------------------------|------------------|-------------------------|------------|
| Loretta Trujillo | Finance Director | <i>Loretta Trujillo</i> | 02-16-2023 |

Requires OSA approval? (Y/N) Yes Request sent: _____ Approval Received _____ Attach related documents
 Requires DFA approval? (Y/N) Yes Request sent: _____ Approval Received _____ Attach related documents
 Requires Commission approval? (Y/N) Yes Approval Received _____ Attach related documents

Attach Disposal results (ie proof of destruction, sales proceeds, other)
 Original completed form to Asset Coordinator, Finance Department
 Copy to Departmental Asset Committee Member

*State Statutes specific to computer equipment apply



TOTAL LOSS EVALUATION

CLAIM HANDLER: RANDY CHAVEZ
 CLAIM NUMBER: 8086
 FILE NUMBER: **2642469**
 INSURED: VALENCIA CNTY
 OWNER:
 UNIT: 2007 FORD F 250

VIN NUMBER: 1FTSF21P87EB22696
 ENGINE/HORSE POWER:
 TRANSMISSION:
 MILES: 95440
 OTHER:

| | | |
|------------------------|--------------------|--------------------------|
| 1. FROM: AUTOTRADER | \$18,950.00 | LISTING |
| | | 2007 FORD F250 88505MI |
| | | ADJ FOR MILEAGE/ INTERIC |
| | | AND SERVICE BED |
| PHONE: 571-590-5603 | -\$500.00 | |
| Adjusted Listing Value | \$3,000.00 | |
| | \$22,450.00 | |
| 2. FROM: AUTOTRADER | \$13,550.00 | LISTING |
| | | 2007 F-250 158007 MI |
| | | ADJUSTMENT FOR MILEAG |
| | | SERVICE BED |
| PHONE: (812) 920-4925 | \$1,000.00 | |
| Adjusted Listing Value | \$3,000.00 | |
| | \$17,550.00 | |
| 3. FROM : AUTOTRADER | \$19,950.00 | LISTING |
| | | 2007 F-250 51892MI |
| | | ADJUSTMENT FOR MILEAG |
| | | AND UTILITY BED |
| PHONE: 602-338-2002 | -\$2,500.00 | |
| Adjusted Listing Value | \$3,000.00 | |
| | \$20,450.00 | |

ACV **\$20,150.00**

SALVAGE BIDS

| COMPANY | NUMBER | CONTACT | AMOUNT |
|-----------------|--------------|---------|------------|
| ACE SALVAGE | 505-877-6293 | ROGER | \$1,650.00 |
| A AND A SALVAGE | 505-242-9358 | BALDO | \$1,500.00 |
| 5J'S | 505-877-6270 | RJ | \$0.00 |
| | | | |



Alliance Appraisals Inc

Workfile ID:

889fc131

For Supplements: alliance-appraisals.com
39 Avenida Alegre
Los Lunas, NM 87031
Phone: (505) 688-7731
alliance.appraisal@outlook.com

Preliminary Supplement 1 with Summary

Owner: VALENCIA COUNTY

Job Number:

Written By: Chris Jester
Adjuster: RANDY, CHAVEZ

Insured: VALENCIA COUNTY
Type of Loss: Comprehensive
Point of Impact: 15 Total Loss

Policy #:
Date of Loss: 10/11/2022 11:00 AM

Claim #: 008086
Days to Repair: 11

Owner:
VALENCIA COUNTY
1209 Hwy 314
Los Lunas, NM 87031
(505) 238-6928 Business

Inspection Location:
1209 Hwy 314
1209 Hwy 314
Los Lunas, NM 87031
Other

Repair Facility:
COLOR WORKS
1920 E MAIN
LOS LUNAS, NM 87031
(505) 865-6863 Business

VEHICLE

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

VIN: 1FTSF21P87EB22696
License: G68468
State:

Production Date:
Odometer: 95,440
Condition:

Interior Color:
Exterior Color: White

TRANSMISSION

Overdrive
6 Speed Transmission
4 Wheel Drive

POWER

Power Steering
Power Brakes

DECOR

Dual Mirrors

Tinted Glass

CONVENIENCE

Intermittent Wipers
Message Center

RADIO

AM Radio
FM Radio
Stereo
Search/Seek

SAFETY

Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes

SEATS

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

TRUCK

Rear Step Bumper
Trailer Hitch
Trailer Package

Preliminary Supplement 1 with Summary

Owner: VALENCIA COUNTY

Job Number:

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|------|--------------------------------------------------|--------------|-----|-------------------|---------|-------|
| 1 | | FRONT BUMPER | | | | | |
| 2 | | O/H front bumper | | | | 1.6 | |
| 3 | <> | Repl Bumper F250, F350 paint to matc | 5C3Z17757CAA | 1 | 445.87 | Incl. | 1.7 |
| 4 | | Add for Clear Coat | | | | | 0.7 |
| 5 | | FENDER | | | | | |
| 6 | * | Rpr RT Fender F250, F350 | | | | 1.0 | 2.2 |
| | | Note: REMOVE DECALS AND REPAINT | | | | | |
| 7 | | Overlap Major Non-Adj. Panel | | | | | -0.2 |
| 8 | | Add for Clear Coat | | | | | 0.4 |
| 9 | R&I | RT Fender liner | | | | 0.6 | |
| 10 | * | Rpr LT Fender F250, F350 | | | | 5.0 | 2.2 |
| | | Note: REMOVE DECAL AND REPAIR DENT | | | | | |
| 11 | | Overlap Major Non-Adj. Panel | | | | | -0.2 |
| 12 | | Add for Clear Coat | | | | | 0.4 |
| 13 | R&I | LT Fender liner | | | | 0.6 | |
| 14 | * | R&I RT Nameplate "F250 XL SUPER DUTY" | | | | 0.2 | |
| 15 | * | R&I LT Nameplate "F250 XL SUPER DUTY" | | | | 0.2 | |
| 16 | | TRANSMISSION | | | | | |
| 17 | * | Repl Clutch 6.0 liter B75% | 7C3Z7550C | 1 | 336.92 | 1.0 M | |
| | | Note: shop states clutch is out | | | | | |
| 18 | | Repl Pressure plate 6.0 liter B75% | 7C3Z7550C | 1 | 336.92 | | |
| 19 | | Repl Hub & bearing clutch release | 3C3Z7548AA | 1 | 67.50 | | |
| 20 | R&I | R&I transmission manual trans 4WD | | | | m 5.0 M | |
| 21 | | STEERING COLUMN | | | | | |
| 22 | | Repl Ignition cyl | 1L3Z11582A | 1 | 104.00 m | 0.1 M | |
| 23 | | Repl Ignition cyl retainer | F2DZ3C610A | 1 | 17.33 | | |
| 24 | | CAB | | | | | |
| 25 | Blnd | RT Corner panel | | | | | 0.6 |
| 26 | Blnd | LT Corner panel | | | | | 0.6 |
| 27 | | INSTRUMENT PANEL | | | | | |
| 28 | | Repl RT Air outlet vent center black | 5C3Z19893BAA | 1 | 35.67 | | |
| 29 | * | Repl Switch assy deactivating, passenger air bag | F81Z14B268AA | 1 | 147.67 | 0.5 M | |
| | | Note: INCLUDES WIRE REPAIR | | | | | |
| 30 | | FRONT DOOR | | | | | |
| 31 | * | Rpr RT Outer panel w/o keyless en | | | | 2.0 | 2.5 |
| | | Note: REMOVE DECAL FOR REFINISH | | | | | |
| 32 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 33 | | Add for Clear Coat | | | | | 0.4 |
| 34 | * | Rpr LT Outer panel w/o keyless en | | | | 2.0 | 2.5 |

Preliminary Supplement 1 with Summary

Owner: VALENCIA COUNTY

Job Number:

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

| | | | | | | | | | |
|---------------------------------|-----|----------------------------------------------------|---------------|---|------------------|---|-------------|-------------|------|
| Note: REMOVE DECAL FOR REFINISH | | | | | | | | | |
| 35 | | Overlap Major Adj. Panel | | | | | | | -0.4 |
| 36 | | Add for Clear Coat | | | | | | | 0.4 |
| 37 | R&I | RT Belt w/strip | | | | | 0.3 | | |
| 38 | R&I | LT Belt w/strip | | | | | 0.3 | | |
| 39 | * | Repl LKQ RT Mirror w/paddle swing lock manual +25% | F81Z17682AAA | 1 | 93.75 | | 0.6 | | |
| 40 | R&I | LT Mirror w/paddle swing lock manual | | | | | 0.6 | | |
| 41 | * | Repl LKQ RT Handle, outside black +25% | 7C3Z2522404AA | 1 | 73.75 | | 0.3 | 0.0 | |
| 42 | * | Repl LKQ LT Handle, outside black +25% | 7C3Z2522405AA | 1 | 73.75 | | 0.3 | 0.0 | |
| 43 | R&I | RT Lock cylinder | | | | | 0.1 | | |
| 44 | R&I | LT Lock cylinder | | | | | 0.1 | | |
| 45 | R&I | RT R&I trim panel | | | | | 0.5 | | |
| 46 | R&I | LT R&I trim panel | | | | | 0.5 | | |
| 47 | # | Subl Hazardous waste removal | | 1 | 5.00 | T | | | |
| 48 | # | Repl Cover Car | | 1 | 5.00 | T | | | |
| 49 | # | Color tint / color match | | 1 | | | | 0.5 | |
| 50 | # | Subl Two wheel alignment | | 1 | 79.99 | T | | | |
| 51 | # | S01 Repl UTILITY BED +25% | | 1 | 8,750.00 | | | | |
| 52 | # | S01 Subl LABOR TO INSTALL | | 1 | 800.00 | X | | | |
| SUBTOTALS | | | | | 11,373.12 | | 23.4 | 13.9 | |

NOTES

Prior Damage Notes:
none

Preliminary Supplement 1 with Summary

Owner: VALENCIA COUNTY

Job Number:

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

ESTIMATE TOTALS

| Category | Basis | Rate | Cost \$ |
|-------------------------------|----------------|--------------|------------------|
| Parts | | | 10,483.13 |
| Body Labor | 16.8 hrs @ | \$ 55.00 /hr | 924.00 |
| Paint Labor | 13.9 hrs @ | \$ 55.00 /hr | 764.50 |
| Mechanical Labor | 6.6 hrs @ | \$ 85.00 /hr | 561.00 |
| Paint Supplies | 13.9 hrs @ | \$ 36.00 /hr | 500.40 |
| Miscellaneous | | | 889.99 |
| Subtotal | | | 14,123.02 |
| Sales Tax | \$ 13,323.02 @ | 7.8750 % | 1,049.19 |
| Total Cost of Repairs | | | 15,172.21 |
| Deductible | | | 0.00 |
| Clutch 6.0 liter B75% | | | 272.59 |
| Pressure plate 6.0 liter B75% | | | 272.59 |
| Total Adjustments | | | 545.18 |
| Net Cost of Repairs | | | 14,627.03 |

MyPriceLink Estimate ID / Quote ID:

1015009753069264896 / 113863336

Preliminary Supplement 1 with Summary

Owner: VALENCIA COUNTY

Job Number:

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

SUPPLEMENT SUMMARY

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|----------------------|------|------------------------------------|-------------|-----|-------------------|-------------|-------------|
| Deleted Items | | | | | | | |
| 47 | # | Rpr LEFT SIDE UTILITY BED MID DOOR | | | | -1.5 | -3.0 |
| 48 | # | Repl RT UTILITY BED MID DOOR | | 1 | -347.56 | -2.0 | -3.0 |
| 49 | # | Repl LFT UTILITY BED DOOR FRONT | | 1 | -486.98 | -2.0 | -3.0 |
| 50 | # | Repl UTILITY ROOF LIGHT BAR | | 1 | -365.32 | -2.0 | |
| Added Items | | | | | | | |
| 51 | # | S01 Repl UTILITY BED +25% | | 1 | 8,750.00 | | |
| 52 | # | S01 Subl LABOR TO INSTALL | | 1 | 800.00 X | | |
| SUBTOTALS | | | | | 8,350.14 | -7.5 | -9.0 |

CHANGES TO ADJUSTMENTS

TOTALS SUMMARY

| Category | Basis | Rate | Cost \$ |
|--------------------------------|---------------|--------------|-----------------|
| Parts | | | 7,550.14 |
| Body Labor | -7.5 hrs @ | \$ 55.00 /hr | -412.50 |
| Paint Labor | -9.0 hrs @ | \$ 55.00 /hr | -495.00 |
| Paint Supplies | -9.0 hrs @ | \$ 36.00 /hr | -324.00 |
| Miscellaneous | | | 800.00 |
| Subtotal | | | 7,118.64 |
| Sales Tax | \$ 6,318.64 @ | 7.8750 % | 497.91 |
| Additional Supplement Taxes | | | -0.31 |
| Total Supplement Amount | | | 7,616.24 |
| NET COST OF SUPPLEMENT | | | 7,616.24 |

MyPriceLink Estimate ID / Quote ID:

1015009753069264896 / 113863336

Preliminary Supplement 1 with Summary

Owner: VALENCIA COUNTY

Job Number:

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

CUMULATIVE EFFECTS OF SUPPLEMENT(S)

| | | |
|-----------------------------|---------------------|--------------|
| Estimate | 7,555.97 | Chris Jester |
| Supplement S01 | 7,616.24 | Chris Jester |
| Workfile Total: | \$ 15,172.21 | |
| TOTAL ADJUSTMENTS: | \$ 545.18 | |
| NET COST OF REPAIRS: | \$ 14,627.03 | |

ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR PAYMENT OF A LOSS OR BENEFIT OR KNOWINGLY PRESENTS FALSE INFORMATION IN AN APPLICATION FOR INSURANCE IS GUILTY OF A CRIME AND MAY BE SUBJECT TO CIVIL FINES AND CRIMINAL PENALTIES.

Preliminary Supplement 1 with Summary

Owner: VALENCIA COUNTY

Job Number:

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DE2ME99, CCC Data Date 02/08/2023, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS Information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) Items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blend=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Supplement 1 with Summary

Owner: VALENCIA COUNTY

Job Number:

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

PARTS SUPPLIER LIST

| Line | Supplier | Description | Price |
|-------------|--------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|
| 39 | M&M BODY ARTURO MARQUEZ 5925 EDITH BLVD NE ALBUQUERQUE NM 87107 (505) 345-7200 | #000183 LKQ RT Mirror w/paddle swing lock manual +25% Side Mirror, Rt RT SIDE MIRROR-NICE | \$ 150.00 |
| 41 | LKQ OF NEW MEXICO SANDY BLALOCK 5701 BROADWAY S.E. ALBUQUERQUE NM 87105 (800) 469-0665 | #\$AR387 LKQ RT Handle, outside black +25% Door Handle, Rt Ft RH,XL,2DR R, DOOR, (HANDLE ASSEMBLY), FRONT, R., BLACK TEXTURED, W/KEY S#\$AR387 | \$ 59.00 |
| 42 | LKQ OF NEW MEXICO SANDY BLALOCK 5701 BROADWAY S.E. ALBUQUERQUE NM 87105 (800) 469-0665 | #W07269 LKQ LT Handle, outside black +25% Door Handle, Lt Ft LH,XLT,4DR L, TAILGATE, W/TAILGATE LOCKS#W07269 | \$ 59.00 |

Claim Summary

Owner: VALENCIA COUNTY

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

Insurance Company

| | | |
|---------------|-----------|--------------|
| Company: | Claim #: | 008086 |
| Claim Office: | Adjuster: | CHAVEZ RANDY |
| Address: | Policy #: | |
| Phone: | | |

Appraisal Company

| | | | |
|------------|-------------------------|------------|--------------|
| Company: | Jester Appraisals | Estimator: | Chris Jester |
| IA Office: | Alliance Appraisals Inc | | |
| Address: | 39 Avenida Alegre | | |
| | Los Lunas, NM 87031 | | |
| Phone: | (505) 688-7731 | | |

Vehicle Owner

| | | | |
|----------|---------------------|------------|----------------|
| Insured: | VALENCIA COUNTY | Loss Type: | Comprehensive |
| Owner: | VALENCIA COUNTY | Business: | (505) 238-6928 |
| | 1209 Hwy 314 | | |
| | Los Lunas, NM 87031 | | |

Vehicle Information

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

| | | | | | |
|-------------------------|-------------------|------------------|-----------------|-----------------|-------|
| VIN: | 1FTSF21P87EB22696 | Production Date: | Interior Color: | | |
| License: | G68468 | Odometer: | 95,440 | Exterior Color: | White |
| State: | | Condition: | | | |
| Primary Impact Point: | Total Loss | | | Drivable: | No |
| Secondary Impact Point: | | | | | |

Inspection Information

| | |
|----------------------|---------------------|
| Place of Inspection: | 1209 Hwy 314 |
| Address: | 1209 Hwy 314 |
| | Los Lunas, NM 87031 |

Claim Summary

Owner: VALENCIA COUNTY

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

Estimate to Repair

| | |
|-----------------------------|---------------------|
| Estimate | \$ 14,123.02 |
| Taxable Subtotal | \$ 14,123.02 |
| Tax | 1,049.19 |
| Non-Taxable Subtotal | \$ 15,172.21 |
| Betterment | 545.18 |
| Deductible | 0.00 |
| Appearance Allowance | 0.00 |
| 0% Negligence | 0.00 |
| Calculated Net Loss | \$ 14,627.03 |

LKQ Parts Included
A/M Parts Not Included
Opt OEM Parts Not Included
Recond Parts Not Included

Total Loss Valuation

| | |
|-------------------------------|----------------|
| Vehicle Valuation | \$ 0.00 |
| Supp. Taxable Adjustments | 0.00 |
| Taxable Subtotal | \$ 0.00 |
| Tax | 0.00 |
| Supp. Non-Taxable Adjustments | 0.00 |
| Non-Taxable Subtotal | \$ 0.00 |
| Owner Retained Salvage | 0.00 |
| Deductible | 0.00 |
| 0% Negligence | 0.00 |
| Calculated Net Loss | \$ 0.00 |

Vehicle Valuation Request#

Settlement Information

Settlement Type: Undetermined

Comments

Inspected on 10-28-22

N/A

Damages: The service bed fenders and doors

UPD: N/A

Repairable: Owners choice of shop. The vehicle is repairable, possible supplement for Mechanical Issues

Agreed price: No shop chosen

Betterment: Was taken on the rear tire of 75% on clutch and pressure plate

Total Loss: N/A

Parts Usage: LKQ and aftermarket parts were considered in this report and were cost affective.

Loss Description: The damages appear to be consistent with the loss description. Column service bed and cab of truck

Contact for th evillage states the clutch is out on this truck, and thinks theres issues with front end when they drove back to shop

Supp once vehicle in shop and they tried to locate and order the doors for the service bed they are not available needs new service bed and labor which pushed over total loss threshold

Events

| | | |
|------------|---------|-----------------------------------------------------------|
| 10/11/2022 | | Loss occurred |
| 10/27/2022 | 3:51 PM | Requested Recycled Parts. |
| | | Comments: On Demand request of Recycled Part data. |
| 10/27/2022 | 3:51 PM | Recycled Parts added. |
| | | Comments: Recycled Part data files added to the workfile. |
| 10/27/2022 | 4:07 PM | First preliminary estimate line written. |
| 10/27/2022 | 4:21 PM | Payer Type updated - [None] |
| 10/27/2022 | 4:21 PM | Insurance Company updated - NEW MEXICO COUNTIES |

Claim Summary

Owner: VALENCIA COUNTY

2007 FORD Super Duty F-250 XL Regular Cab 137" WB 4WD 2D P/U 8-6.0L Turbocharged Diesel Turbo-Charged OHV White

| | | |
|------------|---------|----------------------------------------------------------------------------------|
| 10/27/2022 | 4:21 PM | Workfile accepted |
| 10/27/2022 | 4:21 PM | Created MyPriceLink quote ID 113863336. |
| 10/31/2022 | 8:19 AM | Requested Recycled Parts. Comments: On Demand request of Recycled Part data. |
| 2/13/2023 | 2:19 PM | Advisor report on estimate requested |
| 2/13/2023 | 2:19 PM | Advisor report on estimate received |
| 2/13/2023 | 2:19 PM | Estimate of Record created. |
| 2/13/2023 | 2:19 PM | Workfile state changed from assigned to inspected. |
| 2/13/2023 | 2:19 PM | Requested Recycled Parts. Comments: On Demand request of Recycled Part data. |
| 2/13/2023 | 2:19 PM | Preliminary Supplement 1 Created. Comments: Preliminary Supplement 1 Created. |
| 2/13/2023 | 2:19 PM | Workfile state changed from inspected to assigned. |
| 2/14/2023 | 1:34 PM | Insurance Company updated - 008086 |
| 2/14/2023 | 1:40 PM | Insurance Company updated - [None] |



Assignment Info

File # : 2642469

Claim # : 008086

Date : 02/15/2023

Alliance Appraisals Inc.

39 Avenida Alegre

Los Lunas, NM 87031

Phone (505) 688-7731

Email alliance.appraisal@outlook.com



ASSET DISPOSAL / TRANSFER FORM

This form is to be used when an asset has been identified as surplus, obsolete, or worn out and is to be disposed of via sale, trade-in, or scrapped.
(Disposal Committee Consensus required)

Use also when an asset is loaned or donated to another governmental organization or to another department within Valencia County.
(Does not require Disposal Committee consensus)

Section A – Departmental Staff Details: Please Print

| Department | Department Director | Department's Asset Coordinator: | |
|------------------|---------------------|---------------------------------|------------|
| | | Last Name | First Name |
| Sheriff's Office | Denise Vigil | Noah, | Jeff |

Section B – Asset Details (may attach alternative documents, as long as all information is included)

Short Description of Disposal or Transfer: Vehicle salvaged. Date of loss 11/23/2022.

Transferring Asset from(Dept) Sheriff's Office to (Dept) NM Counties Multi-Line Claims

| Asset Number, If known | Serial Number / Tag # | Asset Description | Asset Location | Asset had been assigned to: (may need to update HR file) | He / IT approval | If Vehicle: Fleet Manager must sign off | Hard Drive Wiped (not just reformatted)* (Yes/No/NA) |
|--------------------------|-----------------------|--------------------|------------------------|----------------------------------------------------------|------------------|-----------------------------------------|------------------------------------------------------|
| see attached or fill in: | | | | | | | |
| | 1FM5K8ARXHGC07795 | 2017 Ford Explorer | Charlie's Paint & Body | | | | N/A |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

Section C – Disposal Committee members:

To be signed & dated at Disposal Committee Meeting:

| Name of Member #1 | Position | Signature | Date |
|-------------------|----------------------|--------------------|-----------|
| Jeff Noah | Under Sheriff | <i>[Signature]</i> | 2-13-23 |
| Name of Member #2 | Position | Signature | Date |
| Maria Garcia | Indigent Coordinator | <i>[Signature]</i> | 2/10/2023 |
| Name of Member #3 | Position | Signature | Date |
| Kendra Kaneshiro | Accountant | <i>[Signature]</i> | 2/10/2023 |

Section D: To be filled out by Finance Department :

| Name of Person Approving | Position | Signature | Date |
|--------------------------|------------------|--------------------|------------|
| Loretta Trujillo | Finance Director | <i>[Signature]</i> | 02-14-2023 |

Requires OSA approval? (Y/N) Yes Request sent: --- Approval Received --- Attach related documents
 Requires DFA approval? (Y/N) Yes Request sent: --- Approval Received --- Attach related documents
 Requires Commission approval? (Y/N) Yes Approval Received --- Attach related documents

Attach Disposal results (ie proof of destruction, sales proceeds, other)
 Original completed form to Asset Coordinator, Finance Department
 Copy to Departmental Asset Committee Member

*State Statutes specific to computer equipment apply

NEW MEXICO ASSOCIATION OF COUNTIES
MULTI-LINE DEPARTMENT
NOTICE OF CLAIM

COUNTY: Valencia

DEPARTMENT INVOLVED: Sheriff's Office

County Contact: Maria Eugenia Garcia

Phone Number: 505-866-2016

CLAIM TYPE:

☐ AU: Auto - 1st party
☐ AU: Auto - 3rd party
☒ LE: Law Enforcement
☐ IJ: Injunctive Relief

☐ PR: Property - 1st party
☐ GL: General Liability (3rd party)
☐ CR: Civil Rights (employment)
☐ LU: Land Use

☐ Record Only

DATE OF LOSS/INJURY: 11/23/2022

DATE TCN FILED: N/A

POLICE REPORT: Yes ☒ No ☐ REPORT #: 711004479
(PLEASE FORWARD POLICE REPORT AND ANY PICTURES)

INJURY: Yes ☒ No ☐ INJURY DESCRIPTION: Lip cut open

BRIEFLY DESCRIBE LOSS/INCIDENT: Crash

1ST PARTY AUTO (COUNTY):

Employee Involved in Incident Information:

Vehicle Information:

Name: Joshua Burbank
Date of Birth: 1997
Social Security Number: _____
Occupation/Title: Deputy
Status of Employment: Active
Employee Phone Number: 505.866.2400
Drivers License Number: _____

Year: 2017
Make: Ford
Model: 00210G
License Plate #: !
VIN #: 1FM5K8ARXHGC07795
Serial #: _____

1ST PARTY PROPERTY (COUNTY):

Location (name of building): _____
Physical Address: _____
Action taken by County: _____

3RD PARTY CLAIM (CLAIMANT OR INVOLVED WITH 1ST PARTY CLAIM):
(AU, GL, LE, CR, IJ, LU)

X-REFERENCE WITH 1st PARTY AUTO CLAIM #: _____

Claimant Information:

Vehicle Information:

Name: _____
Address: _____
City, State, Zip: _____
Phone(s): _____
E-mail: _____
Insurance Carrier & Policy Number: _____
Attorney Information: _____

Year: _____
Make: _____
Model: _____
License Plate #: _____
VIN #: _____
Serial #: _____

Submitted by: Maria Eugenia Garcia

Date Submitted: 12/8/2022

List of Attachments: Notice of Claim, Police Report, Estimate



CHARLIES PAINT & BODY

925 MARTHA JEAN RD, BELEN, NM 87002

Phone: (505) 864-4444

FAX: (505) 864-6280

Workfile ID:

PartsShare:

8196380f

753zW7

Preliminary Estimate

Customer: Valencia County Sheriffs Office

Job Number:

Written By: Front Desk

Insured: Valencia County Sheriffs Office

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair: 0

Point of Impact:

Owner:

Valencia County Sheriffs Office
(505) 866-2400 Cell

Inspection Location:

CHARLIES PAINT & BODY
925 MARTHA JEAN RD
BELEN, NM 87002
Repair Facility
(505) 864-4444 Business

Insurance Company:

VEHICLE

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

VIN: 1FM5K8ARXHGC07795

Interior Color:

Mileage In: 130,657

Vehicle Out:

License: 00210G

Exterior Color: Black

Mileage Out:

State: NM

Production Date:

Condition:

Job #:

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering

Power Brakes

Power Windows

Power Locks

Power Mirrors

Power Driver Seat

Power Adjustable Pedals

DECOR

Dual Mirrors

Privacy Glass

Overhead Console

CONVENIENCE

Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Rear Defogger

Message Center

Steering Wheel Touch Controls

Rear Window Wiper

Backup Camera

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

CD Player

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Xenon or L.E.D. Headlamps

SEATS

Cloth Seats

Bucket Seats

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

Rear Spoiler

California Emissions

Preliminary Estimate

Customer: Valencia County Sheriffs Office

Job Number:

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

| Line | Oper | Description | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|-------|------------------------------------------------------|---------------|-----|-------------------|-------|-------|
| 1 | | FRONT BUMPER | | | | | |
| 2 | | O/H front bumper | | | | 3.8 | |
| 3 | ** <> | Repl A/M CAPA Bumper cover | FB5Z17D957EB | 1 | 601.00 | Incl. | 2.4 |
| 4 | | Add for Clear Coat | | | | | 1.0 |
| 5 | # | R&I Push Bar | | | | 3.0 | |
| 6 | | FRONT LAMPS | | | | | |
| 7 | | Repl LT Headlamp housing level 2 lamps to 04/03/2018 | FB5Z13008AD | 1 | 1,074.13 | Incl. | |
| 8 | | Aim headlamps | | | | 0.5 | |
| 9 | | FENDER | | | | | |
| 10 | ** | Repl A/M CAPA LT Fender | FB5Z16006A | 1 | 290.00 | 2.3 | 2.2 |
| 11 | | Overlap Major Non-Adj. Panel | | | | | -0.2 |
| 12 | | Add for Clear Coat | | | | | 0.4 |
| 13 | | Add for Edging | | | | | 0.5 |
| 14 | | R&I LT Fender liner | | | | Incl. | |
| 15 | | Repl LT Wheel flare | FB5Z16039AB | 1 | 65.07 | 0.3 | |
| 16 | | Repl LT Insulator | BG1Z16B127B | 1 | 12.42 | Incl. | |
| 17 | | PILLARS, ROCKER & FLOOR | | | | | |
| 18 | | Repl LT Rocker molding | FB5Z7810177AA | 1 | 191.70 | 0.5 | |
| 19 | * | Repl LT Aperture panel | FB5Z78211A11B | 1 | 586.90 | 18.0 | 4.0 |
| 20 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 21 | | Add for Clear Coat | | | | | 0.7 |
| 22 | | R&I LT Wndshld plr trim camel/gray | | | | Incl. | |
| 23 | | R&I LT Wndshld plr trim ebony w/o PLATINUM | | | | Incl. | |
| 24 | | R&I LT Uptr ctr plr trim ebony | | | | Incl. | |
| 25 | | R&I LT Lwr ctr plr trim ebony | | | | Incl. | |
| 26 | | R&I LT Scuff plate front, w/o illumination ebony | | | | Incl. | |
| 27 | | R&I LT Scuff plate rear ebony | | | | Incl. | |
| 28 | | FRONT DOOR | | | | | |
| 29 | # | Repl Door Harness | GB5Z14631A | 1 | 123.50 | 1.0 M | |
| 30 | * | Repl LKQ LT door assy +25% | J85Z7820125B | 1 | 1,493.75 | 1.8 | 3.4 |
| 31 | | Overlap Major Adj. Panel | | | | | -0.4 |
| 32 | * | Add for Clear Coat | | | | | 0.6 |
| 33 | | Repl LT Door w/strip | BB5Z7820531A | 1 | 183.97 | 0.4 | |
| 34 | | R&I LT W/strip on body | | | | Incl. | |
| 35 | | Repl LT Belt w/strip | BB5Z7821453A | 1 | 88.97 | 0.3 | |
| 36 | | Repl LT Lower molding carbon black | FB5Z7820879AB | 1 | 225.27 | 0.4 | |
| 37 | | Repl LT Mirror outside power, w/power fold w/o lamps | DB5Z17683XJ | 1 | 350.53 | 0.3 | |
| 38 | * | Repl LT Run channel | J85Z7821597A | 1 | Incl. | 0.3 | |
| 39 | * | Repl LT Lower guide | BB5Z7821573B | 1 | Incl. | Incl. | |

Preliminary Estimate

Customer: Valencia County Sheriffs Office

Job Number:

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

| | | | | | | | | |
|----|--------------------------|------|------------------------------------------------------|---------------|---|----------|-------|------|
| 40 | * | Repl | LKQ LT Door glass FORD POLICE INTERCEPTOR +25% | BB5Z7821411B | 1 | Incl. | 0.5 | |
| 41 | * | Repl | LKQ LT Window motor w/o memory seat +25% | EB5Z7823395A | 1 | Incl. m | 0.2 | |
| 42 | * | Repl | LKQ LT Window regulator +25% | BB5Z7823209A | 1 | Incl. | 1.1 | |
| 43 | | Repl | LT Handle, outside black | BB5Z7822404AA | 1 | 39.38 | 0.4 | |
| 44 | | Repl | LT Handle base w/o passive entry | BT4Z7826685A | 1 | 62.68 | 0.3 | |
| 45 | | Repl | LT Lock cyl assy w/POLICE INTERCEPTOR | DB5Z5421990A | 1 | 60.85 | 0.1 | |
| 46 | | Repl | LT Latch w/o passive entry | DG1Z5421813A | 1 | 130.03 | 0.3 | |
| 47 | | Repl | LT Remote rod | BB5Z7822153A | 1 | 15.47 | 0.2 | |
| 48 | | Repl | LT Striker | 7T4Z7822008B | 1 | 31.03 | Incl. | |
| 49 | | Repl | LT Door check | BB5Z7823552A | 1 | 27.27 | 0.2 | |
| 50 | | Repl | LT Upper hinge | BB5Z7822801C | 1 | 34.28 | 0.3 | 0.3 |
| 51 | * | | Add for Clear Coat | | | | | 0.1 |
| 52 | | Repl | LT Upper hinge bolt M8x17mm | W710603S439 | 1 | 2.75 | | |
| 53 | | Repl | LT Upper hinge bolt M10x30mm | W705201S439 | 1 | 2.75 | | |
| 54 | | Repl | LT Lower hinge | BB5Z7822811B | 1 | 31.43 | 0.3 | 0.3 |
| 55 | * | | Add for Clear Coat | | | | | 0.1 |
| 56 | | Repl | LT Upper hinge nut | W709450S438 | 2 | 5.50 | | |
| 57 | | Repl | LT Lower hinge hinge pin | W715134S439 | 1 | 2.75 | | |
| 58 | | Repl | LT Lower hinge bolt M8x17mm | W710603S439 | 1 | 2.75 | | |
| 59 | | Repl | LT Lower hinge bolt M10x30mm | W705201S439 | 1 | 2.75 | | |
| 60 | | Repl | LT Lower hinge nut | W709450S438 | 2 | 5.50 | | |
| 61 | * | Repl | LKQ LT Door trim panel POLICE INTERCEPTOR ebony +25% | FB5Z7823943GA | 1 | 176.25 | 0.6 | |
| 62 | * | R&I | LT Handle, inside POLICE INTERCEPTOR | | | | 0.2 | |
| 63 | REAR DOOR | | | | | | | |
| 64 | | R&I | LT W'strip on body | | | | Incl. | |
| 65 | * | Repl | LKQ LT door assy +25% | FB5Z7824631A | 1 | 1,287.50 | 5.6 | 3.5 |
| 66 | | | Overlap Major Adj. Panel | | | | | -0.4 |
| 67 | * | | Add for Clear Coat | | | | | 0.6 |
| 68 | | R&I | LT Door w'strip | | | | 0.4 | |
| 69 | * | Repl | LT Lower molding carbon black insert | FB5Z7825557AA | 1 | 210.83 | Incl. | |
| 70 | QUARTER PANEL | | | | | | | |
| 71 | | Blnd | LT Quarter panel | | | | | 1.3 |
| 72 | | R&I | LT Splash shield | | | | 0.3 | |
| 73 | | R&I | LT Wheel opng mldg | | | | 0.4 | |
| 74 | | R&I | LT Upper molding | | | | 0.3 | |
| 75 | REAR LAMPS | | | | | | | |
| 76 | | R&I | LT Tail lamp assy level 1 | | | | 0.3 | |
| 77 | REAR BUMPER | | | | | | | |
| 78 | | R&I | R&I bumper cover | | | | 1.2 | |
| 79 | RESTRAINT SYSTEMS | | | | | | | |

Preliminary Estimate

Customer: Valencia County Sheriffs Office

Job Number:

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

| | | | | | | | | |
|------------------|---------------------------------|--------------------------------------------------------|---------------|---|------------------|---|-------------|-------------|
| 80 | Repl | RT Head air bag | D85Z78042D94A | 1 | 581.40 | m | 0.6 | M |
| 81 | | Air bag system diagnosis ck system operation | | | | m | 0.5 | M |
| 82 | | Air bag system diagnosis pinpoint test | | | | m | 2.1 | M |
| 83 | Repl | LT Head air bag | D85Z78042D95A | 1 | 653.85 | m | 0.6 | |
| 84 | Repl | RT Ft seat air bag w/Police Interceptor w/o power seat | BG1Z54611D10A | 1 | 292.83 | m | 0.7 | |
| 85 | Repl | Control module | HB5Z148321A | 1 | 481.58 | m | 0.3 | |
| 86 | Repl | LT Side Impact sens front | GN1Z14B345A | 1 | 42.93 | m | 0.3 | |
| 87 | Repl | LT Side Impact sens rear | FR3Z14B004A | 1 | 45.64 | m | 0.3 | |
| 88 | # | Subl Airbag Programing | | 1 | 160.00 | | | |
| 89 | # | Trip Charge to Dealership | | 1 | 50.00 | | | |
| 90 | SEATS & TRACKS | | | | | | | |
| 91 | R&I | RT R&I front seat | | | | | 0.5 | |
| 92 | R&I | LT R&I front seat | | | | | Incl. | |
| 93 | R&I | R&I second row seat bench seat | | | | | Incl. | |
| 94 | Repl | RT Seat back cover charcoal | FG1Z5464416PB | 1 | 241.05 | | 1.2 | |
| 95 | Repl | RT Seat back pad | FG1Z5464B10A | 1 | 177.05 | | | |
| 96 | ROOF | | | | | | | |
| 97 | Repl | Headliner w/o rear AC ebony | FB5Z7851944FC | 1 | 2,141.25 | | 4.7 | |
| 98 | VEHICLE DIAGNOSTICS | | | | | | | |
| 99 | * | Rpr Pre-repair scan | | | | m | 0.5 | M |
| 100 | * | Rpr Post-repair scan | | | | m | 0.5 | M |
| 101 | MISCELLANEOUS OPERATIONS | | | | | | | |
| 102 | * | Repl Cover car/bag | | 1 | 5.00 | | 0.2 | |
| 103 | # | FLEX ADDITIVE CROMAX PAINT | | 1 | 8.00 | | | |
| 104 | # | CORROSION PROTECTION | | 1 | 15.00 | | 0.5 | |
| 105 | # | HAZARDOUS MATERIAL | | 1 | 5.00 | | | |
| 106 | # | R&I Emergency Equipment | | | | | 7.0 | |
| | | Note: includes R&I cages and lights | | | | | | |
| 107 | # | SET-UP & MEASURE | | 1 | | | 2.0 | |
| 108 | # | BODY PULLS | | 1 | | | 2.0 | F |
| 109 | # | Repl Decals | | 1 | 175.00 | | 1.0 | |
| 110 | # | Repl Harness attaches to door harness | HB5Z14A005BA | 1 | 801.67 | | 6.0 | M |
| 111 | OTHER CHARGES | | | | | | | |
| 112 | # | Towing | | 1 | 548.20 | | | |
| SUBTOTALS | | | | | 13,844.41 | | 77.6 | 20.0 |

Preliminary Estimate

Customer: Valencia County Sheriffs Office

Job Number:

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

ESTIMATE TOTALS

| Category | Basis | Rate | Cost \$ |
|------------------|---------------|--------------|-----------|
| Parts | | | 13,296.21 |
| Body Labor | 64.4 hrs @ | \$ 55.00 /hr | 3,542.00 |
| Paint Labor | 20.0 hrs @ | \$ 55.00 /hr | 1,100.00 |
| Mechanical Labor | 11.2 hrs @ | \$ 95.00 /hr | 1,064.00 |
| Frame Labor | 2.0 hrs @ | \$ 95.00 /hr | 190.00 |
| Paint Supplies | 20.0 hrs @ | \$ 38.00 /hr | 760.00 |
| Other Charges | | | 548.20 |
| Subtotal | | | 20,500.41 |
| Sales Tax | \$ 6,444.20 @ | 8.3125 % | 535.67 |
| Grand Total | | | 21,036.08 |
| Deductible | | | 0.00 |
| CUSTOMER PAY | | | 0.00 |
| INSURANCE PAY | | | 21,036.08 |

MyPriceLink Estimate ID / Quote ID:

1028110258280603648 / 115656171

ESTIMATE BASED ON OUR INSPECTION THERE MAY BE ADDITIONAL DAMAGE OR PARTS WHICH MAY BE REQUIRED.

THIS WORK AUTHORIZED BY _____.

ANY PERSON WHO KNOWINGLY PRESENTS A FALSE OR FRAUDULENT CLAIM FOR PAYMENT OF A LOSS OR BENEFIT OR KNOWINGLY PRESENTS FALSE INFORMATION IN AN APPLICATION FOR INSURANCE IS GUILTY OF A CRIME AND MAY BE SUBJECT TO CIVIL FINES AND CRIMINAL PENALTIES.

Preliminary Estimate

Customer: València County Sheriffs Office

Job Number:

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR2MF16, CCC Data Date 12/01/2022, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2023 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blend=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Preliminary Estimate

Customer: Valencia County Sheriffs Office

Job Number:

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

PARTS SUPPLIER LIST

| Line | Supplier | Description | Price |
|------|-----------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| 3 | National Autobody Parts Warehouse 2000 E Main Street Grand Prairie TX 75050 (800) 214-7222 | #FO1000723C A/M CAPA Bumper cover Quote: 1384496239 Expires: 12/12/22 | \$ 601.00 |
| 10 | Keystone 3800 Prince St. SE ALBUQUERQUE NM 87105 (505) 341-2300 | #FO1240301PP A/M CAPA LT Fender Quote: 1515685011 Expires: 01/19/23 | \$ 290.00 |
| 30 | LKQ Corp 5701 Broadway SE Albuquerque NM 87105 (505) 873-0665 | #~319034804 LKQ LT door assy +25% Door Assembly, Front Sport, w/o memory driver seat; L,S#\$E0774 Quote: 1516903025 Expires: 01/20/23 | \$ 1,195.00 |
| 40 | LKQ Corp 5701 Broadway SE Albuquerque NM 87105 (505) 873-0665 | #~332037788 LKQ LT Door glass FORD POLICE INTERCEPTOR +25% Door Glass, Front XLT,4DR L, BASE, W/O POLICE PACKAGE; L,S#\$P0420 Quote: 1516935522 Expires: 01/20/23 | \$ 125.00 |
| 41 | LKQ Corp 5701 Broadway SE Albuquerque NM 87105 (505) 873-0665 | #~304843265 LKQ LT Window motor w/o memory seat +25% Power Window Motor XLT,4DR,PW L, FRONT, XLT, L,S#\$AR358 Quote: 1516945731 Expires: 01/20/23 | \$ 40.00 |
| 42 | LKQ Corp 5701 Broadway SE Albuquerque NM 87105 (505) 873-0665 | #~252962242 LKQ LT Window regulator +25% Door Window Regulator, Front INTERCEPTOR,4DR,PW L, (WITHOUT MOTOR), L,S#\$PL502 Quote: 1516943503 Expires: 01/20/23 | \$ 35.00 |
| 61 | LKQ Corp 5701 Broadway SE Albuquerque NM 87105 (505) 873-0665 | #~237464810 LKQ LT Door trim panel POLICE INTERCEPTOR ebony +25% Trim Panel, Front Door POLICE ,5DR,9W,BLK,PW L, ASSY, POLICE INTERCEPT,S#\$EZ357 Quote: 1516965414 Expires: 01/20/23 | \$ 141.00 |
| 65 | LKQ Corp | #~320513867 | \$ 1,030.00 |

Preliminary Estimate

Customer: Valencia County Sheriffs Office

Job Number:

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

5701 Broadway SE
Albuquerque NM 87105
(505) 873-0665

LKQ LT door assy +25%
Door Assembly, Rear (ELECTRIC), PRIVACY TINT GLASS, EXC.
POLICE PKG, L.,S#\$AT110
Quote: 1516992124
Expires: 01/20/23

Preliminary Estimate

Customer: Valencia County Sheriffs Office

Job Number:

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

RECALL INFO

2017 FORD Police Interceptor Utility Vehicle AWD (Fleet) 4D UTV 6-3.7L Gasoline Sequential MPI Black

| | | | |
|------------------------|-----------------------|---------------------|--------------|
| VIN: 1FMSK8ARXHGC07795 | Interior Color: | Mileage In: 130,657 | Vehicle Out: |
| License: 00210G | Exterior Color: Black | Mileage Out: | |
| State: NM | Production Date: | Condition: | Job #: |

The National Highway Transportation and Safety Administration (NHTSA) has issued 3 safety-related recall notice(s) that may apply to the selected vehicle.

NHTSA ID: 17V530000 Issued: Aug 8, 17 Number of Vehicles: 00000253

STEERING Ford Motor Company (Ford) is recalling certain 2017 Explorer, Taurus and Police Interceptor Utility and Sedan vehicles. The steering gear heat shield fasteners may corrode, allowing the heat shield to detach. If the heat shield detaches, the steering gear may overheat, increasing the steering effort required by the driver, especially at lower speeds, and increasing the risk of a crash. Ford will notify owners, and dealers to inspect and replace the heat shield fasteners as needed, free of charge. The recall began on September 13, 2017. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17S23.

NHTSA ID: 17V401000 Issued: Jun 6, 17 Number of Vehicles: 00000004

SEATS:MID/REAR ASSEMBLY Ford Motor Company (Ford) is recalling certain 2017 Ford Explorer Police Interceptor vehicles. The affected vehicles may be missing the two front Inboard attachments for the second row seats. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 207, "Seating systems", and (FMVSS) number 210, "Seat belt assembly anchorages." Seats with missing inboard attachments may not adequately restrain an occupant in a crash, increasing the risk of injury. Ford will notify owners, and dealers will inspect the vehicles to verify that they have the second row seat attachment studs, installing them if not, free of charge. The recall began on August 14, 2017. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17C10.

NHTSA ID: 16V925000 Issued: Dec 12, 16 Number of Vehicles: 00001163

ENGINE AND ENGINE COOLING:ENGINE:GASOLINE:TURBO/SUPERCHARGER Ford Motor Company (Ford) is recalling certain model year 2016 Ford Taurus, 2016-2017 Ford Flex, Lincoln MKT, 2017 Ford Explorer and Ford Explorer Police Interceptor Utility vehicles equipped with 3.5L GTDI engines. Improperly brazed turbocharger oil supply tubes may leak oil on engine components. An oil leak, in the presence of an ignition source, increases the risk of a fire. Ford will notify owners, and dealers will inspect, and if necessary, replace the turbocharger oil supply tubes, free of charge. The recall began on January 31, 2017. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 16S46.